PROCESS FLOW CHART FOR AXIAL LEAD DIODE

二極管工序流程圖



01=MATERIAL INCOMING INSPECTION
來料檢查

02=PRODUCTION OF LEAD WIRE
引線生產

03=ASSEMBLING
裝配

04=GLASS SEALING
玻封

05=SOLDER DIPPING
浸錫

06=CLEANING
清洗

07=100% TESTING AND MARKING
100%測試，嘜字

08=SECOND TIME 100% TESTING AND TAPING
二次100%測試，上帶

09=PACKING
包裝

10=FINAL INSPECTION BEFORE DISPATCHING
出廠驗收檢查

QA=QUALITY ASSURANCE
最終檢查

S1=STORAGE
倉儲

C1=QUALITY CONTROL AND MONITORING OF LEAD WIRE
引線IPQC過程檢查及控制

C2=QUALITY CONTROL AND MONITORING OF GLASS SEALING
玻封品質控制

C3=QUALITY CONTROL AND MONITORING OF SOLDER DIPPING
浸錫品質控制

C4=QUALITY CONTROL AND MONITORING OF MARKING
嘜字品質檢查及控制

C5=QUALITY CONTROL AND MONITORING OF TAPING
上帶品質檢查及控制